

## HT-CALIPSO Firmware

---

---

### Firmware Version:

Formal firmware version — v1.3.35, file name “HT-CALIPSO-WHOLE-V1.3.35.ENC.tar.gz”

**Release Date:** 2023/08/18

### Release Notes:

- New requirements
    1. Build-in HT-Voyager firmware to 1.1.23.
  
  - Other known issues
    1. When device works in Split screen mode and Miracast/airplay screen as the extended screen of PC, there will be a long black time when switching.
    2. When work under low resolution, the OSD icon of MUTE \ tracking mode is larger than normal icon.
- 
- 

### Firmware Version:

Formal firmware version — v1.3.14, file name “HT-CALIPSO-WHOLE-V1.3.14.ENC.tar.gz”

**Release Date:** 2023/03/17

### Release Notes:

- New requirements
  1. HT-CALIPSO Product name change (from HT-MERCURY).GB-334
  
- Issues fixed.
  1. Fixed the issue that when disconnecting the Type-C source and automatically powering off the TV, and then reconnecting it, it may not be able to trigger the TV to power on.
  2. Fixed the issue that when casting, and reconnecting the HDMI output to a TV that supports 4K60, the casting doesn't come out.
  
- Other known issues
  1. When device works in Split screen mode and Miracast/airplay screen as the extended screen of PC, there will be a long black time when switching.
  2. When work under low resolution, the OSD icon of MUTE \ tracking mode is larger than normal icon.

**Note:** After upgrading from FW v1.2.36 to FW v1.3.14, it needs to restore the factory settings.

---

---

### Firmware Version:

Formal firmware version —— v1.2.36, file name “HT-MERCURY-WHOLE-V1.2.36.ENC.tar.gz”

**Release Date:** 2022/12/14

**Release Notes:**

- New requirements
  1. Factory reset button, clicking the button on the side 5 times in quick succession to achieve it.GB-239
  2. Standby countdown can be adjusted on the web. GB-263
- Optimization
  1. Optimize Auto framing, slight body shaking will not change framing.
  2. Optimize Speaker Tracking, speed up the switching time and merge the switching effect, smooth/immediate configuration have been removed.
  3. Improve the face recognition accuracy rate.
  4. Optimize Speaker Tracking, when no one is talking, auto framing will be used to frame the screen
  5. Optimize the volume output and make it smoother.GB-238
- Issues fixed
  1. Fixed the issue that "Pairing Failed" is spelled incorrectly.GB-255
- Other known issues
  1. When device works in Split screen mode and Miracast/airplay screen as the extended screen of PC, there will be a long black time when switching.
  2. When work under low resolution, the OSD icon of MUTE \ tracking mode is larger than normal icon.

---

---

**Firmware Version:**

Formal firmware version —— v1.2.22, file name “HT-MERCURY-WHOLE-V1.2.22.ENC.tar.gz”

**Release Date:** 2022/09/19

**Release Notes:**

- New requirement
    1. WEB UI replaced the high-resolution logo file as required.
- 
-